

## VEHICLE INSPECTION REPORT

LP68ACJ

### Mercedes-Benz A Class A180d Sport Executive 5dr Auto

Inspection	Vehicle	nama GRADE 4
Serious Damage?	VAT	Margin
No	V5	Present

#### Details

Reg. date	30/11/2018	Body Style	Hatchback	Last service miles	57,291
Year	2018	Keys	2	MOT Due	29/11/2026
Mileage	64,677 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	GREY	Number of stamps	3	Doors	5
VIN	WDD1770032V011466	Last service date	18/02/2025		

£100 ADDITIONAL FEE.

Last service 18/02/2025 at 57,291 miles- 3 services. Print

#### Tyres


NSF	BRIDGESTONE	4.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Front parking sensor
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
Over 100mm Thru Paint



2: Boot Lid  
Dented  
Over 2 UpTo 10mm



3: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm

No Image

4: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



5: Wheel osr  
Scratched  
Up To 50mm



6: Door osr  
Scratched  
Over 25mm Thru Paint



7: Door osf  
Chipped  
Edge Chip



8: Door osf  
Dented  
Over 2 UpTo 10mm



9: Wing osf  
Chipped  
1 To 5



10: Wheel osf  
Scratched  
Up To 50mm



11: Bumper Front  
Scratched  
25 to 100mm Thru Paint

No Image

12: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



13: Bonnet  
Chipped  
1 To 5

No Image

14: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



15: Wheel nsf  
Scratched  
Up To 50mm



16: Door nsf  
Scratched  
Over 25mm Thru Paint



17: Door nsr  
Dented  
With Paint Damage



18: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



19: Wheel nsr  
Scratched  
Up To 50mm

## Interior

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK