

VEHICLE INSPECTION REPORT

GU62HSV

Citroen C4 Picasso 1.6 HDi Platinum 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 5

Details

Reg. date	16/10/2012
Year	2012
Mileage	109,822 Miles Warranted
Fuel Type	Diesel
Colour	SILVER
VIN	VF7UD9HR8CJ723008

Body Style	MPV
Keys	1
Service history	Yes
Service documents	Service Book
Number of stamps	6
Last service date	16/09/2022

Last service miles	88,883
MOT Due	21/09/2026
Gearbox	MANUAL
Gears	6

Last service 16/09/2022 at 88,883 miles- 6 services (5 main dealer). Book and Print DPF and starter motor fault
Heavy vibration at idle

Tyres

NSF	BUDGET	4.0mm
NSR	PIRELLI	4.0mm
OSF	BUDGET	4.0mm
OSR	PIRELLI	3.0mm
Spare		

Features


- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
UpTo 25mm



2: Other
N/A
N/A



3: Other
N/A
N/A



4: Bonnet
Chipped
1 To 5




5: Bumper Front
Poor Previous Repair
Poor Paint



6: Wing nsf
Chipped
1 To 5



7: Wing nsf
Scratched
Over 25mm Not Thru Paint



8: Screen Front
Chipped
UpTo 10mm




9: Wheel nsf
Scratched
Over 50mm



10: Door nsf
Chipped
Multiple Chips



11: Door nsr
Chipped
1 To 5



12: Door nsr
Scratched
Over 25mm Not Thru Paint



13: Wheel nsr
Scratched
Over 50mm



14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Bumper Rear
Scratched
Over 100mm Thru Paint



16: Boot Lid
Chipped
1 To 5




17: Qtr Panel osr
Scratched
Over 25mm Thru Paint



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Chipped
Multiple Chips




20: Door osf
Chipped
Multiple Chips



21: Wing osf
Cracked
Replace



22: Wheel osf
Scratched
Over 50mm



23: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK