

# VEHICLE INSPECTION REPORT

GL22JXB

## MG Mg 5 EXCLUSIVE

### Inspection

Serious Damage? No

### Vehicle

VAT	Margin
V5	Present

nama  
GRADE  
2

### Details

Reg. date	20/06/2022
Year	2022
Mileage	89,541 Miles Warranted
Fuel Type	Electric
Colour	RED
VIN	LSJE24097NG041289

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	6
Last service date	17/12/2025

Last service miles	88,642
MOT Due	19/06/2026
Gearbox	AUTOMATIC
Gears	1

### £65 ADDITIONAL FEE

Last service 17/12/2025 at 88,642 miles- 6 main dealer services. Print No charging cables

### Tyres


NSF	TOYO	5.0mm
NSR	TOYO	5.0mm
OSF	TOYO	5.0mm
OSR	TOYO	5.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips




2: Bumper Front Grill  
Broken  
Replace




3: Bumper Front  
Chipped  
Multiple Chips

No Image

4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Door nsf  
Chipped  
1 To 5



6: Door nsr  
Scratched  
UpTo 25mm Thru Paint



7: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



8: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



9: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



10: Door osr  
Dented  
Between 10mm + 30mm



11: Door osf  
Scratched  
UpTo 25mm Thru Paint



12: Wing nsf  
Chipped  
1 To 5

## Interior

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK