

## VEHICLE INSPECTION REPORT

KR55LZO

### Ford Focus 1.6 LX 5dr [115]

Inspection	Vehicle		GRADE 5
Serious Damage?	VAT	Margin	
No	V5	Present	

#### Details

Reg. date	06/01/2006	Body Style	Hatchback	Last service miles	152,228
Year	2006	Keys	1	MOT Due	14/01/2027
Mileage	158,636 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	GREEN	Number of stamps	1	Doors	5
VIN	WF05XXGCD55D22806	Last service date	19/06/2024		

Last service 19/06/2024 at 152,228 miles- 1 service. Print EML light on car has been plugged in and detects ho2s heater control circuit bank 1 sensor 1

Nsf headlight has condensation

Knocking from front suspension and bonnet release missing

#### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	Worn
OSF	CONTINENTAL	5.0mm
OSR	YOKOHAMA	4.0mm
Spare		

## Features


- PAS
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Remote central locking
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Cloth seat trim
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Steel wheels
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Bumper Front Moulding  
Broken  
Replace

4: Wing nsf  
Dented  
With Paint Damage



5: Door nsf  
Chipped  
Multiple Chips

6: Sill ns  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Dented  
With Paint Damage

8: Roof  
Poor Previous Repair  
Paint Flake



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Bumper Rear  
Poor Previous Repair  
Paint Flake



11: Boot Lid  
Dented  
Between 10mm + 30mm

No Image

12: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



13: Qtr Panel osr  
Dented  
With Paint Damage



14: Door osr  
Poor Previous Repair  
Poor Paint



15: Door osf  
Dented  
Over 30mm



16: Moulding osf Wing  
Broken  
Replace



17: Wing osf  
Chipped  
Multiple Chips



18: Screen Front  
Chipped  
UpTo 10mm

## Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK