

VEHICLE INSPECTION REPORT

LC09FVP

Volkswagen Tiguan 2.0 TDi Sport 5dr Auto

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 5

Details

Reg. date	08/05/2009
Year	2009
Mileage	70,698 Miles Warranted
Fuel Type	Diesel
Colour	GREY
VIN	WVGZZZ5NZ9W065942

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	10
Last service date	04/04/2025

Last service miles	62,412
MOT Due	07/04/2026
Gearbox	AUTOMATIC
Gears	6

£100 ADDITIONAL FEE

Last service 04/04/2025 at 62,412 miles- 10 services (8 main dealer) Book and print Engine misfire under load

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	2.0mm
OSR	PIRELLI	3.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Roof Lining
Torn
Over 3mm



2: Bonnet
Chipped
Multiple Chips




3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Dented
With Paint Damage



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Scratched
Over 25mm Thru Paint




8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
Over 30mm



10: Bumper Rear
Chipped
Multiple Chips




11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Chipped
Multiple Chips



13: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Wheel osr
Scratched
Over 50mm




16: Door osr
Dented
Over 30mm



17: Door osf
Dented
With Paint Damage



18: Roof
Poor Previous Repair
Poor Paint



19: Wing osf
Dented
Over 30mm



20: Screen Front
Chipped
UpTo 10mm



21: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Poor
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		