

VEHICLE INSPECTION REPORT

HN66OJZ

Fiat 500x 1.6 E-torQ Lounge 5dr [Start Stop]

Inspection	Vehicle	nama GRADE 4
Serious Damage?	VAT	Margin
No	V5	Present

Details

Reg. date	26/11/2016	Body Style	Hatchback	Last service miles	103,754
Year	2016	Keys	1	MOT Due	21/10/2026
Mileage	106,212 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	8	Doors	5
VIN	ZFA3340000P519041	Last service date	18/11/2025		

£100 ADDITIONAL FEE

Last service 18/11/2025 at 103,754 miles- 8 services (2 main dealer) Book and print Heavy vibration at idle

Tyres

NSF	BUDGET	4.0mm
NSR	AUTOGREEN	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Audio remote control
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Poor Previous Repair
Poor Colour




3: Wheel nsf
Scratched
Over 50mm

4: Wing nsf
Chipped
1 To 5



5: Door nsf
Chipped
1 To 5

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Dented
2 Or Less UpTo 10mm

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Up To 50mm




10: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



11: Bumper Rear
Cracked
UpTo 25mm



12: Boot Lid
Poor Previous Repair
Poor Paint




13: Qtr Panel osr
Chipped
1 To 5




14: Wheel osr
Scratched
Up To 50mm



15: Door osr
Chipped
1 To 5



16: Door osf
Chipped
1 To 5




17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Wing osf
Dented
Over 2 UpTo 10mm



19: Wheel osf
Scratched
Over 50mm



20: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK