

VEHICLE INSPECTION REPORT

EF15JVH

Fiat 500x 1.4 Multiair Cross 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Buyer To Apply

nama
GRADE 5

Details

Reg. date	30/06/2015
Year	2015
Mileage	121,810 Miles Warranted
Fuel Type	Petrol
Colour	WHITE
VIN	ZFA3340000P357370

Body Style	Hatchback
Keys	1
Service history	Yes
Service documents	Service Book
Number of stamps	2
Last service date	29/01/2020

Last service miles	40,692
MOT Due	17/10/2026
Gearbox	MANUAL
Gears	6
Doors	5

£65 ADDITIONAL FEE.

Last Service - 29.01.2020 at 40692 miles (2 services)

NO V5

Tyres



NSF	BUDGET	2.0mm
NSR	MICHELIN	2.0mm
OSF	MICHELIN	2.0mm
OSR	BUDGET	Worn
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Partial leather seat trim
- Cruise control
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- PAS
- Audio remote control
- Climate control
- Rear electric windows
- ABS
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Poor Previous Repair
Paint Flake




3: Qtr Panel osr
Dented
With Paint Damage



4: Wheel osr
Scratched
Over 50mm



5: Door osr
Dented
With Paint Damage



6: Door osf
Dented
2 Or Less UpTo 10mm



7: Door osf
Chipped
1 To 5



8: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



9: Wing osf
Chipped
1 To 5



10: Wheel osf
Scratched
Over 50mm



11: Screen Front
Chipped
UpTo 10mm



12: Bumper Front
Poor Previous Repair
Poor Colour



13: Bonnet
Dented
With Paint Damage



14: Wing nsf
Chipped
1 To 5



15: Wheel nsf
Scratched
Over 50mm



16: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint




17: Door nsf
Poor Previous Repair
Poor Paint



18: Door nsr
Dented
With Paint Damage



19: Qtr Panel nsr
Chipped
1 To 5



20: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



21: Wheel nsr
Scratched
Over 50mm



22: Seat Base Cover osf
Torn
Over 3mm



23: Seat Base Cover nsf
Torn
Over 3mm



24: Handle Outer osf
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK