

## VEHICLE INSPECTION REPORT

EO11FRL

### Ford Grand C-Max 2.0 TDCi Titanium 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 5

#### Details

Reg. date	03/03/2011
Year	2011
Mileage	96,341 Miles Warranted
Fuel Type	Diesel
Colour	BLACK
VIN	WF0HXXWPBHB68079

Body Style	MPV
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	06/09/2023

Last service miles	74,730
MOT Due	05/09/2026
Gearbox	MANUAL
Gears	6

Last service 06/09/2023 at 74,730 miles- 8 services. Book Steering knocking

#### Tyres



NSF	CONTINENTAL	Damaged
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Headrest Assy Rear Seat ns  
Missing  
Replace



2: Bonnet  
Scratched  
Over 25mm Thru Paint



3: Bumper Front Grill  
Broken  
Replace



4: Bumper Front  
Hole  
Over 25mm



5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Door nsr  
Dented  
Between 10mm + 30mm



9: Door nsr  
Scratched  
Over 25mm Thru Paint



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



13: Wheel osr  
Scratched  
Over 50mm



14: Door osr  
Dented  
With Paint Damage



15: Door osf  
Scratched  
Over 25mm Thru Paint



16: Wing osf  
Scratched  
Over 25mm Thru Paint



17: Wheel osf  
Scratched  
Over 50mm



18: Screen Front  
Chipped  
UpTo 10mm



19: Roof  
Chipped  
Over 5mm



20: Tyre nsf  
Damaged  
Replace



21: Badgedecal Rear

Missing  
Replace

#### Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

### Vehicle Inspection Report

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	Fault