

## VEHICLE INSPECTION REPORT

OV58GXW

### Honda FR-V 1.8 i-VTEC EX 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 5

#### Details

Reg. date	23/10/2008
Year	2008
Mileage	136,543 Miles Warranted
Fuel Type	Petrol
Colour	BLUE
VIN	JHMBE17608S205782

Body Style	MPV
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	06/10/2016

Last service miles	66,403
MOT Due	02/02/2026
Gearbox	MANUAL
Gears	6

£100 ADDITIONAL FEE.

Last service 06/10/2016 at 66,403 miles- 8 main dealer services. Book

#### Tyres


NSF	AVON	4.0mm
NSR	AVON	4.0mm
OSF	AVON	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Cruise control
- Radio/CD
- Climate control
- Metallic Paint
- Passenger airbag
- Alloy wheels
- PAS
- Body coloured bumpers
- Front electric windows
- 3x3 point rear seat belts
- Central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- ABS
- Remote central locking
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wing nsf  
Dented  
With Paint Damage



4: Wheel nsf  
Scratched  
Over 50mm



5: Door Mirror Assy nsf  
Broken  
Replace



6: Door nsf  
Chipped  
Multiple Chips



7: Door nsr  
Chipped  
Multiple Chips



8: Wheel nsr  
Scratched  
Over 50mm




9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Bumper Rear  
Chipped  
Multiple Chips



11: Boot Lid  
Chipped  
Multiple Chips



12: Qtr Panel osr  
Dented  
Over 30mm



13: Door osr  
Dented  
With Paint Damage



14: Wheel osr  
Scratched  
Over 50mm



15: Door osf  
Chipped  
Multiple Chips



16: Wing osf  
Poor Previous Repair  
Poor Paint



17: Wheel osf  
Scratched  
Over 50mm



18: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK