

## VEHICLE INSPECTION REPORT

**GX67MTE**

### Kia Sportage 1.7 CRDi ISG 3 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 4

#### Details

Reg. date	02/09/2017
Year	2017
Mileage	131,742 Miles Warranted
Fuel Type	Diesel
Colour	SILVER
VIN	U5YPH815GL197059

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	12
Last service date	28/02/2025

Last service miles	127,248
MOT Due	21/10/2026
Gearbox	MANUAL
Gears	6

£100 ADDITIONAL FEE.

Last service 28/02/2025 at 127,248 miles- 12 services (10 main dealer) Book Front suspension knocking

#### Tyres


NSF	SUNNY	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
1 To 5



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Chipped  
Edge Chip



6: Door nsr  
Chipped  
1 To 5



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



10: Tailgate  
Dented  
Over 30mm



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



12: Wheel osr  
Scratched  
Over 50mm




13: Other  
N/A  
N/A




14: Door osf  
Dented  
Between 10mm + 30mm



15: Wheel osf  
Scratched  
Over 50mm



16: Roof  
Chipped  
Edge Chip



17: Screen Front  
Cracked  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK