

VEHICLE INSPECTION REPORT

OV13UAP

Audi A6 Allroad 3.0 TDI Quattro 204 5dr S Tronic

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	27/06/2013
Year	2013
Mileage	80,152 Miles Warranted
Fuel Type	Diesel
Colour	BLUE
VIN	WAUZZZ4G9DN150221

Body Style	Estate
Keys	1
Service history	Yes
Service documents	Printout
Number of stamps	3
Last service date	20/03/2023

Last service miles	74,143
MOT Due	10/09/2026
Gearbox	AUTOMATIC
Gears	7

Last service 20/03/2023 at 74143 miles (3 services (2 main dealer)).

Tyres

NSF	ACCELERA	5.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	ACCELERA	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belt
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Dented
Over 2 UpTo 10mm



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Dented
2 Or Less UpTo 10mm

No Image

9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Chipped
1 To 5

No Image

11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Dented
With Paint Damage



14: Bumper Rear Moulding
Broken
Replace



15: Boot Lid
Dented
Over 2 UpTo 10mm

No Image

16: Boot Lid
Scratched
Over 25mm Not Thru Paint



17: Qtr Panel osr
Chipped
1 To 5

No Image

18: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



19: Wheel osr
Scratched
Over 50mm

20: Door osr
Rusted
Over 5mm





21: Sill Panel Trim os
Scuffed (Unpainted)
UpTo 100mm

22: Door osf
Scratched
UpTo 25mm Thru Paint



23: Screen Front
Chipped
UpTo 10mm

24: Wing osf
Chipped
1 To 5



25: Wing osf
Scratched
Over 25mm Not Thru Paint

26: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK