

VEHICLE INSPECTION REPORT

GK18FFJ

Nissan Qashqai 1.6 DiG-T Tekna 5dr

Inspection	Vehicle		GRADE 2
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	07/03/2018	Body Style	Hatchback	Last service miles	17,020
Year	2018	Keys	2	MOT Due	06/03/2026
Mileage	63,619 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	2	Doors	5
VIN	SJNFCAJ11U2213709	Last service date	27/08/2020		

£65 ADDITIONAL FEE

Last service 27/08/2020 at 17,020 miles- 2 main dealer services. Book Eml on - car plugged in and read (02 circuit high voltage bank 1 sensor 2

Tyres


NSF	BUDGET	2.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Radio/CD
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



No Image

5: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Chipped
1 To 5

No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint




9: Door nsr
Chipped
1 To 5

No Image

10: Door nsf
Scratched
Over 25mm Not Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



13: Bumper Rear
Chipped
Multiple Chips

No Image


14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Boot Lid
Dented
Over 2 UpTo 10mm



16: Qtr Panel osr
Chipped
1 To 5




17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Wheel osr
Corroded
Light



19: Door osr
Dented
Over 2 UpTo 10mm



20: Door osr
Scratched
Over 25mm Not Thru Paint



21: Door osf
Chipped
1 To 5

No Image

22: Door osf
Scratched
Over 25mm Not Thru Paint



23: Wing osf
Chipped
1 To 5



24: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		