

## VEHICLE INSPECTION REPORT

GL62CAV

### Citroen DS3 1.6 VTi 16V DStyle Plus 3dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 3

#### Details

Reg. date	06/01/2013
Year	2013
Mileage	81,077 Miles Warranted
Fuel Type	Petrol
Colour	WHITE
VIN	VF7SA5FS0CW591867

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	5
Last service date	12/09/2024

Last service miles	71,047
MOT Due	20/09/2026
Gearbox	MANUAL
Gears	5
Doors	3

Last service 12/09/2024 at 71,047 miles- 5 services. Print Noisy clutch ( flywheel)

#### Tyres

NSF	BUDGET	5.0mm
NSR	RAPID	5.0mm
OSF	BUDGET	5.0mm
OSR	RAPID	5.0mm
Spare		

## Features


<ul style="list-style-type: none"> <li>Bluetooth connection</li> <li>Rear wiper</li> <li>Electric door mirrors</li> <li>Front armrest</li> <li>Rear headrests</li> <li>3x3 point rear seat belts</li> <li>Isofix child seat anchor points</li> <li>Remote central locking</li> </ul>	<ul style="list-style-type: none"> <li>Cruise control</li> <li>Service indicator</li> <li>Front fog lights</li> <li>Front electric windows</li> <li>Steering wheel rake adjustment</li> <li>ABS</li> <li>Passenger airbag</li> <li>Cloth seat trim</li> </ul>	<ul style="list-style-type: none"> <li>PAS</li> <li>Radio/CD</li> <li>Air conditioning</li> <li>Front head restraints</li> <li>Steering wheel reach adjustment</li> <li>Drivers airbag</li> <li>Side airbags</li> <li>Alloy wheels</li> </ul>	<ul style="list-style-type: none"> <li>Rear parking sensor</li> <li>Body coloured bumpers</li> <li>Folding rear seats</li> <li>Height adjustable drivers seat</li> <li>Metallic Paint</li> <li>ESP</li> <li>Central locking</li> </ul>
--	---	---	--

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
1 To 5



3: Wing nsf  
Chipped  
1 To 5



4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Dented  
Between 10mm + 30mm



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Bumper Rear  
Chipped  
1 To 5



10: Qtr Panel osr  
Dented  
Between 10mm + 30mm



11: Wheel osr  
Scratched  
Over 50mm



12: Door osf  
Dented  
2 Or Less UpTo 10mm



13: Door osf  
Chipped  
1 To 5



14: Door osf  
Scratched  
UpTo 25mm Thru Paint



15: Wheel osf  
Scratched  
Over 50mm



16: Wing osf  
Chipped  
1 To 5



17: Screen Front  
Chipped  
UpTo 10mm



18: Roof  
Poor Previous Repair  
Paint Flake

## Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK