

VEHICLE INSPECTION REPORT

LF19ALB

Ford Mondeo 1.5 EcoBoost 165 Titanium Edition 5dr

Inspection

Serious Damage? No

Vehicle

VAT	VAT Qualifying
V5	TBC

nama
GRADE 4

Details

Reg. date	24/07/2019
Year	2019
Mileage	87,876 Miles Warranted
Fuel Type	Petrol

Colour	GREY
VIN	WF0EXXWPCEKY58084
Body Style	Hatchback
Keys	2

MOT Due	04/02/2026
Gearbox	MANUAL
Gears	6
Doors	5

Tyres

NSF	AVON	2.0mm
NSR	BUDGET	Worn
OSF	CONTINENTAL	Damaged
OSR	AVON	2.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Chipped
1 To 5



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Poor Previous Repair
Poor Paint



8: Door nsf
Chipped
1 To 5

No Image

9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Chipped
1 To 5

No Image

11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
Over 100mm Thru Paint




14: Bumper Rear Moulding
Broken
Replace



15: Reflector nsr
Broken
Replace




16: Boot Lid
Dented
Over 2 UpTo 10mm



17: Boot Lid
Scratched
Over 25mm Not Thru Paint



18: Qtr Panel osr
Chipped
1 To 5



19: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




20: Wheel osr
Scratched
Over 50mm



21: Door osr
Poor Previous Repair
Poor Paint

22: Door osf
Chipped
1 To 5




23: Door osf
Scratched
Over 25mm Not Thru Paint

24: Wing osf
Chipped
1 To 5



25: Wing osf
Scratched
Over 25mm Not Thru Paint

26: Wheel osf
Scratched
Over 50mm



27: Screen Front
Cracked
Replace



28: Roof
Dented
Between 10mm + 30mm



29: Tyre osf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK