

VEHICLE INSPECTION REPORT

CA09HBL

Vauxhall Astra 1.4i 16V Active Plus 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 5

Details

Reg. date	30/06/2009
Year	2009
Mileage	111,495 Miles Warranted
Fuel Type	Petrol
Colour	RED
VIN	W0L0AHL4898063599

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	7
Last service date	20/05/2017

Last service miles	49,596
MOT Due	Expired
Gearbox	MANUAL
Gears	5
Doors	5

£65 ADDITIONAL FEE

Last Service - 20.05.2017 at 49596 miles (7 services)

MOT EXPIRED EML light is on

Car has been plugged in and detects code o2 heater circuit bank 1 sensor 1

Tyres

NSF	BUDGET	2.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Rear wiper
- Climate control
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Alloy wheels
- Electric door mirrors
- Solid Paint
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
Multiple Chips



3: Door Mirror Assy osf
Broken
Replace



4: Door osf
Chipped
Edge Chip



5: Door osf
Chipped
1 To 5



6: Door osr
Chipped
1 To 5



7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint




9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Other
N/A
N/A



11: Boot Lid
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel nsr
Dented
With Paint Damage



13: Wheel nsr
Scratched
Over 50mm



14: Door nsr
Dented
With Paint Damage




15: Door nsf
Dented
With Paint Damage



16: Sill ns
Dented
With Paint Damage



17: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



18: Wing nsf
Dented
With Paint Damage




19: Wheel nsf
Scratched
Over 50mm



20: Bumper Front
Scratched
Over 100mm Thru Paint



21: Bonnet
Chipped
Multiple Chips




22: Screen Front
Chipped
UpTo 10mm




23: A Post os
Chipped
1 To 5



24: Roof
Chipped
1 To 5



25: A Post ns
Chipped
1 To 5



26: C Post ns
Chipped
1 To 5



27: Lamp osr

Broken

Replace

Interior

Carpet Condition

Average

Seat Condition

Average

Upholstery Condition

Average

Odour

No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK