

## VEHICLE INSPECTION REPORT

LX64NJJ

### Vauxhall Zafira 2.0 CDTi [165] SRi 5dr Auto

Inspection	Vehicle	nama GRADE 4
Serious Damage?	VAT	Margin
No	V5	Present

#### Details

Reg. date	02/09/2014	Body Style	MPV	Last service miles	92,175
Year	2014	Keys	2	MOT Due	11/09/2026
Mileage	94,892 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	11		
VIN	W0LPD9EN3E2102821	Last service date	12/09/2025		

£65 ADDITIONAL FEE.

Last Service - 12.09.2025 at 92175 miles (11 services)

Timing Belt Replaced 27.08.2021 @ 56992 miles Service required message displayed

#### Tyres

NSF

NSR

OSF

OSR



Spare

## Features


- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Front parking sensor
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Remote central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Traction control
- Cloth seat trim
- Rear parking sensor
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Switches And Controls  
Broken  
Replace



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front Moulding  
Broken  
Replace



4: Bumper Front  
Chipped  
Multiple Chips



5: Wing osf  
Dented  
With Paint Damage



6: Wheel nsf  
Scratched  
Over 50mm



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Door nsr  
Scratched  
Over 25mm Thru Paint



9: Wheel nsr  
Scratched  
Over 50mm



10: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



11: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



12: Bumper Rear  
Dented  
With Paint Damage



13: Wheel osr  
Scratched  
Over 50mm



14: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



15: Door osr  
Scratched  
Over 25mm Thru Paint



16: Door osf  
Scratched  
UpTo 25mm Thru Paint



17: Wheel osf  
Scratched  
Over 50mm



18: Wing osf  
Dented  
With Paint Damage



19: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK