

## VEHICLE INSPECTION REPORT

CK63YNL

### Peugeot 2008 1.6 e-HDi Allure 5dr EGC

Inspection	Vehicle		GRADE 3
Serious Damage?	VAT	Margin	
No	V5	Present	

#### Details

Reg. date	21/01/2014	Body Style	Hatchback	Last service miles	83,237
Year	2014	Keys	2	MOT Due	19/12/2026
Mileage	110,578 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	4	Doors	5
VIN	VF3CU9HP8DY088421	Last service date	14/12/2022		

Last Service - 14.12.2022 at 83237 miles (4 services) Engine fault - repair needed on dash

Gearbox fault

Service light on

#### Tyres


NSF	BUDGET	3.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	2.0mm
Spare		

## Features


• Bluetooth connection	• Cruise control	• PAS	• Rear parking sensor
• Rear wiper	• Steering wheel mounted controls	• Audio remote control	• Digital radio
• Body coloured bumpers	• Electric door mirrors	• Electric sunroof	• Fixed panoramic glass roof
• Air conditioning	• Climate control	• Front electric windows	• Front head restraints
• Height adjustable drivers seat	• Rear electric windows	• Rear headrests	• Metallic Paint
• 3x3 point rear seat belts	• ABS	• Drivers airbag	• Isofix child seat anchor points
• Passenger airbag	• Side airbags	• Central locking	• Remote central locking
• Leather seat trim	• Alloy wheels		

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Poor Previous Repair  
Poor Paint



3: Wing nsf  
Dented  
Over 2 UpTo 10mm

No Image

4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Dented  
Over 2 UpTo 10mm



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint



8: Door nsr  
Dented  
With Paint Damage



9: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm

No Image

10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Wheel nsr  
Scratched  
Over 50mm



12: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



13: Bumper Rear  
Chipped  
Multiple Chips

No Image

14: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

# No Image

15: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



16: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm




17: Wheel osr  
Scratched  
Over 50mm



18: Door osr  
Dented  
Over 2 UpTo 10mm

# No Image

19: Door osr  
Scratched  
Over 25mm Not Thru Paint



20: Door osf  
Dented  
Over 2 UpTo 10mm

# No Image

21: Door osf  
Scratched  
Over 25mm Not Thru Paint



22: Wing osf  
Chipped  
1 To 5

23: Wing osf  
Scratched  
Over 25mm Not Thru Paint

24: Wheel osf  
Scratched  
Over 50mm



## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK