

## VEHICLE INSPECTION REPORT

GP16SZV

### Ford Fiesta 1.0 EcoBoost Titanium X 5dr Powershift

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 4

#### Details

Reg. date	15/06/2016
Year	2016
Mileage	61,701 Miles Warranted
Fuel Type	Petrol
Colour	GREY
VIN	WF0DXXGAKDGC63188

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	24/02/2025

Last service miles	53,280
MOT Due	23/02/2026
Gearbox	AUTOMATIC
Gears	6
Doors	5

Last Service - 24.02.2025 at 53280 miles (8 services)

#### Tyres



NSF	BUDGET	3.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Partial leather seat trim
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint

# No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5

# No Image


6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Chipped  
1 To 5

# No Image

8: Door nsf  
Scratched  
Over 25mm Not Thru Paint



9: Door nsr  
Chipped  
Multiple Chips



10: Qtr Panel nsr  
Dented  
With Paint Damage



11: Wheel nsr  
Scratched  
Over 50mm



12: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



13: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



14: Boot Lid  
Dented  
Over 2 UpTo 10mm



15: Qtr Panel osr  
Dented  
Over 30mm



16: Wheel osr  
Scratched  
Over 50mm



17: Door osr  
Dented  
With Paint Damage



18: Door osr  
Scratched  
Over 25mm Thru Paint



19: Wing osr  
Dented  
Over 2 UpTo 10mm



20: Wing osr  
Scratched  
Over 25mm Not Thru Paint



21: Wheel osf  
Scratched  
Over 50mm

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK