

VEHICLE INSPECTION REPORT

GU20DFZ

Volkswagen T-Cross 1.0 TSI 115 SE 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 3

Details

Reg. date	09/03/2020
Year	2020
Mileage	99,536 Miles Warranted
Fuel Type	Petrol
Colour	BLACK
VIN	WVGZZZC1ZLY091863

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	8
Last service date	07/11/2024

Last service miles	80,221
MOT Due	11/12/2026
Gearbox	MANUAL
Gears	6
Doors	5

£65 ADDITIONAL FEE

Last Service - 07.11.2024 at 80221 miles (8 main dealer services Service due message displayed
Intermittent clutch fault

Tyres



NSF	BRIDGESTONE	5.0mm
NSR	THREEA	4.0mm
OSF	BRIDGESTONE	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Door osr
Dented
With Paint Damage



12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Wheel osf
Scratched
Over 50mm



14: Switches And Controls
Missing
Replace

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK