

## VEHICLE INSPECTION REPORT

**EY68UNV**

### Ford Transit Connect 1.5 EcoBlue 120ps Limited Van Powershift

#### Inspection

**Serious Damage?** No

#### Vehicle

<b>VAT</b>	Plus VAT
<b>V5</b>	Present

nama  
GRADE 3

#### Details

<b>Reg. date</b>	01/09/2018
<b>Year</b>	2018
<b>Mileage</b>	159,540 Miles Warranted
<b>Fuel Type</b>	Diesel
<b>Colour</b>	SILVER
<b>VIN</b>	WF0RXXWPGRJM02900

<b>Body Style</b>	Panel Van
<b>Keys</b>	1
<b>Service history</b>	Yes
<b>Service documents</b>	Service Book
<b>Number of stamps</b>	4
<b>Last service date</b>	03/07/2022

<b>Last service miles</b>	118,354
<b>MOT Due</b>	31/08/2026
<b>Gearbox</b>	AUTOMATIC
<b>Gears</b>	8

#### £100 ADDITIONAL FEE

Last service 03/07/2022 at miles- 4 services (3 main dealer) Book Driver heated seat


#### Tyres

<b>NSF</b>	BUDGET	5.0mm
<b>NSR</b>	BUDGET	5.0mm
<b>OSF</b>	BUDGET	5.0mm
<b>OSR</b>	BUDGET	5.0mm
<b>Spare</b>		

## Features


- Bluetooth connection
- Digital radio
- Drivers airbag
- Cruise control
- Air conditioning
- Central locking
- Heated front seat
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Metallic Paint

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5




2: Wing osf  
Scratched  
Over 25mm Not Thru Paint



3: Qtr Panel osr  
Dented  
Over 30mm



4: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



5: Qtr Panel nsr  
Dented  
With Paint Damage



6: Door nsr  
Dented  
Over 30mm



7: Boot Lid  
Dented  
2 Or Less UpTo 10mm




8: Door nsf  
Dented  
Over 30mm



9: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint

10: Wing nsf  
Chipped  
Multiple Chips



11: Bumper Front  
Poor Previous Repair  
Paint Flake

12: Bonnet  
Chipped  
Multiple Chips



13: Screen Front  
Chipped  
UpTo 10mm

14: A Post os  
Chipped  
1 To 5



15: Roof  
Chipped  
Multiple Chips



16: A Post ns  
Chipped  
1 To 5

## Interior

Carpet Condition  
Seat Condition

Average  
Average

Upholstery Condition  
Odour

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK