

VEHICLE INSPECTION REPORT

GY14UBM

Toyota Auris 1.6 V-Matic Excel 5dr Multidrive S

Inspection	Vehicle		GRADE 3
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	20/06/2014	Body Style	Hatchback	Last service miles	52,336
Year	2014	Keys	1	MOT Due	19/06/2026
Mileage	55,321 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	BLUE	Number of stamps	3	Doors	5
VIN	SB1ME3JEX0E056050	Last service date	16/04/2025		

Last service 16/04/2025 at 52336 miles (3 services (2 main dealer). Book & print.

Tyres

NSF	CONTINENTAL	4.0mm
NSR	BUDGET	5.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Heated front seat	• Navigation system
• Park assist camera	• PAS	• Rear wiper	• Steering wheel mounted controls
• Audio remote control	• Radio/CD	• Body coloured bumpers	• Electric door mirrors
• Air conditioning	• Climate control	• Front armrest	• Front electric windows
• Front head restraints	• Height adjustable drivers seat	• Rear electric windows	• Rear headrests
• Metallic Paint	• 3x3 point rear seat belts	• ABS	• Drivers airbag
• Isofix child seat anchor points	• Passenger airbag	• Central locking	• Remote central locking
• Partial leather seat trim	• Alloy wheels		

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Over 2 UpTo 10mm

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Scratched
UpTo 25mm Thru Paint

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage




10: Wheel nsr
Scratched
Up To 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Dented
Over 2 UpTo 10mm



14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint


16: Wheel osr
Scratched
Up To 50mm



17: Door osr
Dented
Over 2 UpTo 10mm

No Image

18: Door osr
Scratched
Over 25mm Not Thru Paint



19: Roof
Scratched
Over 25mm Not Thru Paint

20: Door osf
Chipped
1 To 5

No Image

21: Door osf
Scratched
Over 25mm Not Thru Paint



22: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint




23: Wing osf
Chipped
1 To 5

No Image

24: Wing osf
Scratched
Over 25mm Not Thru Paint



25: Wheel osf
Scratched
Over 50mm



26: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK