

## VEHICLE INSPECTION REPORT

**BG19SOA**

### Ford Galaxy 2.0 EcoBlue 150 Titanium 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 4

#### Details

Reg. date	25/07/2019
Year	2019
Mileage	78,691 Miles Warranted
Fuel Type	Diesel
Colour	BLUE
VIN	WF0KXXWPCKKY73352

Body Style	MPV
Keys	1
Service history	Yes
Service documents	Service Book
Number of stamps	4
Last service date	25/09/2025

Last service miles	75,783
MOT Due	03/10/2026
Gearbox	MANUAL
Gears	6

£100 ADDITIONAL FEE.

Last service 25/09/2025 at 75,783 miles- 4 services (3 main dealer) Book and print handbrake fault

Intake pipe disconnected

#### Tyres



NSF	BUDGET	Worn
NSR	MICHELIN	3.0mm
OSF	BUDGET	2.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips

# No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wheel nsf  
Scratched  
Up To 50mm



5: Wing nsf  
Scratched  
UpTo 25mm Thru Paint

# No Image

6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Chipped  
1 To 5

# No Image

8: Door nsf  
Scratched  
Over 25mm Not Thru Paint



9: Door nsr  
Scratched  
Over 25mm Thru Paint



10: Wheel nsr  
Scratched  
Up To 50mm



11: Qtr Panel nsr  
Dented  
With Paint Damage



12: Bumper Rear  
Scratched  
Over 100mm Thru Paint



13: Boot Lid  
Dented  
Over 2 UpTo 10mm




14: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



15: Wheel osr  
Scratched  
Up To 50mm



16: Door osr  
Scratched  
UpTo 25mm Thru Paint



17: Door osr  
Scratched  
Over 25mm Not Thru Paint



18: Door osf  
Scratched  
Over 25mm Thru Paint



19: Wing osf  
Dented  
Between 10mm + 30mm



20: Wheel osf  
Scratched  
Over 50mm



21: Screen Front  
Chipped  
UpTo 10mm



22: Lamp nsr  
Broken  
Replace



23: Lamp osr  
Broken  
Replace

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Fault	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK