

VEHICLE INSPECTION REPORT

LJ12KDN

Vauxhall Astra 1.6i 16V SRi [115] 3dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	30/04/2012
Year	2012
Mileage	76,367 Miles Warranted
Fuel Type	Petrol
Colour	BLUE

VIN	W0L0AHL08B5018162
Body Style	Hatchback
Keys	1
Service history	None
MOT Due	Expired

Gearbox	MANUAL
Gears	5
Doors	3

no service history Oil leak

Glove box broken and water leak in boot

Eml on after being scanned it says p-0134 (02 sensor fault) and p-0301 (cylinder 1 misfire)

Tyres


NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


<ul style="list-style-type: none"> PAS Radio/CD Climate control Rear headrests Drivers airbag Central locking 	<ul style="list-style-type: none"> Rear wiper Body coloured bumpers Front electric windows Metallic Paint Isofix child seat anchor points Remote central locking 	<ul style="list-style-type: none"> Steering wheel mounted controls Electric door mirrors Front head restraints 3x3 point rear seat belts Passenger airbag Cloth seat trim 	<ul style="list-style-type: none"> Audio remote control Air conditioning Height adjustable drivers seat ABS Side airbags Alloy wheels
---	--	---	---

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Insecure
Action Required



4: Wing nsf
Dented
Over 2 UpTo 10mm



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Chipped
Multiple Chips



8: Qtr Panel nsr
Dented
With Paint Damage



9: Sill ns
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Poor Previous Repair
Poor Paint



12: Boot Lid
Dented
Over 2 UpTo 10mm



13: Boot Lid
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Chipped
Multiple Chips



15: Wheel osf
Scratched
Over 50mm



16: Door osf
Scratched
Over 25mm Thru Paint



17: Wing osf
Chipped
Multiple Chips



18: Wheel osf
Scratched
Over 50mm



19: Sill os
Scratched
UpTo 25mm Thru Paint



20: Door Pad osf
Scuffed
UpTo 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK