

VEHICLE INSPECTION REPORT

BT13MFV

Volkswagen Golf 1.6 TDI BlueMotion Tech SE 2dr

Inspection	Vehicle		nama GRADE 4
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	26/07/2013	Body Style	Convertible	Last service miles	46,980
Year	2013	Keys	2	MOT Due	03/04/2026
Mileage	110,455 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	4		
VIN	WVWZZZ1KZEK001721	Last service date	09/01/2020		

Last service 09/01/2020 at 46,980 miles- 4 services. Book

Tyres


NSF	TOYO	Damaged
NSR	TOYO	5.0mm
OSF	TOYO	5.0mm
OSR	TOYO	5.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Front parking sensor	• Heated front seat
• PAS	• Rear parking sensor	• Steering wheel mounted controls	• Radio/CD
• Body coloured bumpers	• Electric door mirrors	• Space saver spare wheel	• Air conditioning
• Front armrest	• Front electric windows	• Front head restraints	• Height adjustable drivers seat
• Rear electric windows	• Rear headrests	• Steering wheel rake adjustment	• Steering wheel reach adjustment
• Metallic Paint	• 3x3 point rear seat belts	• ABS	• Drivers airbag
• ESP	• Isofix child seat anchor points	• Passenger airbag	• Side airbags
• Central locking	• Remote central locking	• Cloth seat trim	• Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsf
Scratched
Over 25mm Thru Paint



7: Wheel nsf
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Boot Lid
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Scratched
UpTo 25mm Thru Paint




13: Door Mirror Assy osr
Broken
Replace



14: Wheel osr
Scratched
Over 50mm



15: Wing osf
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm



17: Tyre nsf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK