

VEHICLE INSPECTION REPORT

AO59FTV

Nissan Note 1.6 Acenta 5dr Auto

Inspection	Vehicle		nama GRADE 4
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	07/10/2009	VIN	SJNFCAE11U2036085	Last service date	09/03/2015
Year	2009	Body Style	MPV	Last service miles	53,936
Mileage	128,741 Miles Warranted	Keys	2	MOT Due	28/02/2026
Fuel Type	Petrol	Service history	Yes	Gearbox	AUTOMATIC
Colour	RED	Number of stamps	3	Gears	4

Last service 09/03/2015 at 53,936 miles- 3 main dealer services confirmed by Wessex Garages Nissan, Bristol
Difficult to change gear from P , switch on side faulty

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- ESP
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Poor Previous Repair
Paint Flake




3: Wheel nsf
Scratched
Up To 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Chipped
1 To 5




6: Door nsr
Dented
Between 10mm + 30mm



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Up To 50mm



9: Qtr Panel nsr
Dented
Over 30mm




10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Tailgate
Dented
Over 30mm



12: Wheel osr
Scratched
Up To 50mm



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Door Moulding osr
Scratched (Painted)
Over 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Wing osf
Poor Previous Repair
Poor Paint



17: Wheel osf
Scratched
Over 50mm

No Image

18: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK