

VEHICLE INSPECTION REPORT

YH61JGU

Nissan Micra 1.2 Acenta 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	23/09/2011
Year	2011
Mileage	54,888 Miles Warranted
Fuel Type	Petrol
Colour	GREY
VIN	MDHFBUK13U0073298

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	3
Last service date	23/01/2016

Last service miles	25,403
MOT Due	07/02/2027
Gearbox	MANUAL
Gears	5
Doors	5

Last Service - 23.12.2016 at 25403 miles (3 services)

Boot struts weak

Tyres




NSF	FALKEN	4.0mm
NSR	BUDGET	4.0mm
OSF	FALKEN	4.0mm
OSR	FALKEN	4.0mm
Spare		

Features


- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Central locking
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- ABS
- Remote central locking

Photos





Condition Check



Damage Photos



1: Boot Lid
Poor Previous Repair
Poor Paint



2: Bumper Rear
Scratched
Over 100mm Thru Paint



3: Qtr Panel osr
Chipped
1 To 5

No Image

4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




5: Wheel osr
Corroded
Light



6: Door osr
Poor Previous Repair
Poor Paint



7: Door osf
Poor Previous Repair
Poor Paint



8: Wing osf
Poor Previous Repair
Poor Paint



9: Wheel osf
Scratched
Up To 50mm



10: Bonnet
Chipped
1 To 5



11: Bumper Front
Poor Previous Repair
Poor Paint



12: Wing nsf
Poor Previous Repair
Poor Paint



13: Wheel nsf
Scratched
Over 50mm




14: Door nsf
Poor Previous Repair
Poor Paint



15: Door nsr
Dented
2 Or Less UpTo 10mm

No Image



17: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

16: Door nsr
Scratched
Over 25mm Not Thru Paint

No Image



19: Wheel nsr
Corroded
Light

18: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK