

VEHICLE INSPECTION REPORT

Y12CJK

BMW 1 Series 118d M Sport 5dr Step Auto

Inspection	Vehicle	nama GRADE 4
Serious Damage?	VAT	Margin
No	V5	Present

Details

Reg. date	31/03/2015	Body Style	Hatchback	Last service miles	118,437
Year	2015	Keys	2	MOT Due	23/10/2026
Mileage	142,542 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	GREY	Number of stamps	4	Doors	5
VIN	WBA1C12040P773041	Last service date	23/10/2023		

Last Service - 24.10.2023 at 1118437 miles (4 services)

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	2.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• PAS	• Rear parking sensor
• Rear wiper	• Steering wheel mounted controls	• Audio remote control	• Radio/CD
• Body coloured bumpers	• Electric door mirrors	• Air conditioning	• Climate control
• Front armrest	• Front electric windows	• Front head restraints	• Height adjustable drivers seat
• Rear electric windows	• Rear headrests	• Metallic Paint	• 3x3 point rear seat belts
• ABS	• Drivers airbag	• Isofix child seat anchor points	• Passenger airbag
• Central locking	• Remote central locking	• Leather seat trim	• Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Poor Previous Repair
Poor Paint



7: Door nsr
Poor Previous Repair
Poor Paint



8: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Chipped
Multiple Chips


10: Wheel nsr
Scratched
Over 50mm

No Image



13: Boot Lid
Chipped
1 To 5

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Chipped
1 To 5

No Image

15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



16: Wheel osr
Scratched
Up To 50mm



17: Door osr
Poor Previous Repair
Poor Paint



18: Door osf
Poor Previous Repair
Poor Paint



19: Wing osf
Dented
Over 2 UpTo 10mm



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK