

VEHICLE INSPECTION REPORT

LP66FOU

Nissan Micra 1.2 N-Tec 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 5

Details

Reg. date	19/12/2016
Year	2016
Mileage	59,122 Miles Warranted
Fuel Type	Petrol
Colour	GREY
VIN	MDHFBUK13U0346821

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	12/12/2025

Last service miles	57,962
MOT Due	18/12/2026
Gearbox	MANUAL
Gears	5
Doors	5

Last Service - 12.12.2025 at 57962 miles (8 services)

Tyres


NSF	RAPID	5.0mm
NSR	RAPID	5.0mm
OSF	RAPID	5.0mm
OSR	RAPID	5.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Front parking sensor	• Navigation system
• PAS	• Rear parking sensor	• Rear wiper	• Steering wheel mounted controls
• Digital radio	• Body coloured bumpers	• Electric door mirrors	• Front fog lights
• Space saver spare wheel	• Air conditioning	• Folding rear seats	• Front electric windows
• Front head restraints	• Height adjustable drivers seat	• Rear headrests	• Steering wheel rake adjustment
• Steering wheel reach adjustment	• Metallic Paint	• 3x3 point rear seat belts	• ABS
• Drivers airbag	• ESP	• Isofix child seat anchor points	• Passenger airbag
• Side airbags	• Tyre pressure monitor	• Central locking	• Remote central locking
• Cloth seat trim	• Alloy wheels		

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Colour




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
Between 10mm + 30mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Sill ns
Dented
With Paint Damage



8: Door nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Dented
With Paint Damage



14: Door osf
Scratched
UpTo 25mm Thru Paint



15: Aerial
Missing
Replace



16: Wing osf
Dented
Between 10mm + 30mm



17: Wing osf
Scratched
Over 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Tailgate
Dented
Over 30mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK