

VEHICLE INSPECTION REPORT

LF19AJR

Ford Focus 1.5 EcoBlue 120 Titanium 5dr

Inspection

Serious Damage? No

Vehicle

VAT	VAT Qualifying
V5	TBC

nama
GRADE 3

Details

Reg. date	23/07/2019
Year	2019
Mileage	91,135 Miles Warranted
Fuel Type	Diesel

Colour	BLUE	MOT Due	06/08/2026
VIN	WF0NXXGCHNKE25628	Gearbox	MANUAL
Body Style	Hatchback	Gears	6
Keys	2	Doors	5


Tyres




NSF	BUDGET	3.0mm
NSR	KORMORAN	4.0mm
OSF	BUDGET	3.0mm
OSR	HANKOOK	2.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Dented
Over 2 UpTo 10mm



3: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

No Image

4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Wheel osr
Scratched
Up To 50mm



6: Door osr
Chipped
1 To 5



7: Door osr
Scratched
Over 25mm Not Thru Paint



8: Door osf
Chipped
1 To 5

No Image

9: Door osf
Scratched
Over 25mm Not Thru Paint




10: Wing osf
Poor Previous Repair
Poor Paint



11: Wheel osf
Scratched
Up To 50mm



12: Screen Front
Chipped
UpTo 10mm



13: Bonnet
Chipped
1 To 5



14: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

15: Bumper Front
Scratched
Over 25mm Not Thru Paint



16: Wheel nsf
Scratched
Up To 50mm



17: Wing nsf
Chipped
1 To 5

No Image

18: Wing nsf
Scratched
Over 25mm Not Thru Paint



19: Door nsf
Chipped
Multiple Chips



20: Door nsr
Chipped
1 To 5

No Image

21: Door nsr
Scratched
Over 25mm Not Thru Paint



22: Qtr Panel nsr
Dented
Between 10mm + 30mm

No Image

23: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



24: Wheel nsr
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK