

VEHICLE INSPECTION REPORT

LG20HUV

Ford Focus 1.5 EcoBoost 150 Active X 5dr

Inspection

Serious Damage? No

Vehicle

VAT	VAT Qualifying
V5	TBC

nama
GRADE 3

Details

Reg. date	20/07/2020
Year	2020
Mileage	71,851 Miles Warranted
Fuel Type	Petrol

Colour	BLUE
VIN	WF0PXXGCHPLB24017
Body Style	Estate
Keys	2

MOT Due	16/03/2026
Gearbox	MANUAL
Gears	6

Tyres



NSF	MAXXIS	2.0mm
NSR	BUDGET	Punctured
OSF	FALKEN	3.0mm
OSR	FALKEN	3.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Heated front seat	• Navigation system
• Park assist camera	• PAS	• Rear wiper	• Steering wheel mounted controls
• Audio remote control	• Digital radio	• Body coloured bumpers	• Electric door mirrors
• Electric sunroof	• Opening panoramic glass roof	• Air conditioning	• Climate control
• Front armrest	• Front electric windows	• Front head restraints	• Height adjustable drivers seat
• Rear electric windows	• Rear headrests	• Metallic Paint	• 3x3 point rear seat belts
• ABS	• Drivers airbag	• Isofix child seat anchor points	• Passenger airbag
• Side airbags	• Traction control	• Central locking	• Remote central locking
• Partial leather seat trim	• Alloy wheels		

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image


2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Boot Lid
Chipped
1 To 5



4: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Wheel osr
Scratched
Up To 50mm



7: Door osr
Dented
With Paint Damage



8: Door osf
Dented
With Paint Damage



9: Wing osf
Chipped
1 To 5




10: Wheel osf
Scratched
Up To 50mm



11: Bonnet
Chipped
1 To 5



12: Bumper Front
Chipped
Multiple Chips



No Image

13: Bumper Front
Scratched
Over 25mm Not Thru Paint



14: Wing nsf
Chipped
1 To 5

No Image

15: Wing nsf
Scratched
Over 25mm Not Thru Paint




16: Wheel nsf
Scratched
Over 50mm



17: Door nsf
Chipped
Multiple Chips



18: Door nsr
Chipped
1 To 5



19: Door nsr
Scratched
Over 25mm Not Thru Paint



20: Wheel nsr
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		