

## VEHICLE INSPECTION REPORT

LF66VFJ

### Ford Mondeo 2.0 TDCi EConetic Zetec 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	VAT Qualifying
V5	TBC

nama  
GRADE 4

#### Details

Reg. date	28/09/2016
Year	2016
Mileage	67,602 Miles Warranted
Fuel Type	Diesel

Colour	BLACK	MOT Due	30/06/2026
VIN	WF0EXXWPCEGD77863	Gearbox	MANUAL
Body Style	Hatchback	Gears	6
Keys	2	Doors	5

#### Tyres


NSF	FALKEN	4.0mm
NSR	FALKEN	4.0mm
OSF	FALKEN	3.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips




2: Bumper Front  
Scratched  
Over 100mm Thru Paint




3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
Multiple Chips



5: Door nsf  
Poor Previous Repair  
Poor Paint



6: Door nsr  
Chipped  
Multiple Chips



7: Qtr Panel nsr  
Dented  
With Paint Damage




8: C Post ns  
Scratched  
UpTo 25mm Thru Paint



9: Wheel nsr  
Scratched  
Over 50mm



10: Bumper Rear  
Chipped  
Multiple Chips



No Image

11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint




12: Boot Lid  
Chipped  
1 To 5



No Image

13: Boot Lid  
Scratched  
Over 25mm Not Thru Paint




14: Qtr Panel osr  
Dented  
With Paint Damage



15: Wheel osr  
Scratched  
Up To 50mm



16: Door osr  
Chipped  
Multiple Chips



17: Door osf  
Chipped  
Multiple Chips



18: Wing osf  
Dented  
Over 2 UpTo 10mm



19: Wing osf  
Scratched  
Over 25mm Not Thru Paint



20: Wheel osf  
Scratched  
Over 50mm



21: Screen Front  
Chipped  
UpTo 10mm

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK