

VEHICLE INSPECTION REPORT

KF68WZV

Toyota Prius 1.8 VVTi Business Edition 5dr CVT

Inspection

Serious Damage? No

Vehicle

VAT	VAT Qualifying
V5	TBC

nama
GRADE 3

Details

Reg. date	08/02/2019
Year	2019
Mileage	77,043 Miles Warranted
Fuel Type	Hybrid Electric

Colour	WHITE
VIN	JTDKB3FU403603546
Body Style	Hatchback
Keys	2

MOT Due	07/02/2026
Gearbox	CVT
Gears	1
Doors	5

Tyres


NSF	FALKEN	3.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	2.0mm
OSR	FALKEN	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Not Thru Paint

Eastbourne Car Auctions

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Dented
2 Or Less UpTo 10mm



8: Door nsr
Dented
Between 10mm + 30mm



9: Qtr Panel nsr
Dented
Over 30mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



13: Door osr
Dented
Between 10mm + 30mm



14: Door osf
Dented
Over 2 UpTo 10mm

No Image



15: Door osf
Scratched
Over 25mm Not Thru Paint

16: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK