

VEHICLE INSPECTION REPORT

LD19FLC

Ford Mondeo 1.5 EcoBoost 165 Titanium Edition 5dr

Inspection

Serious Damage? No

Vehicle

VAT Qualifying

VAT
V5 TBC

nama
GRADE 4

Details

Reg. date	11/03/2019
Year	2019
Mileage	130,292 Miles Warranted
Fuel Type	Petrol

Colour	BLACK
VIN	WF0EXXWPCEKC88237
Body Style	Hatchback
Keys	2

MOT Due	06/01/2027
Gearbox	MANUAL
Gears	6
Doors	5

Bonnet not aligned

Tyres


NSF	FALKEN	5.0mm
NSR	BUDGET	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Space saver spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Fascia Trim
Damaged
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Scratched
UpTo 25mm Thru Paint




8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Tailgate
Scratched
Over 25mm Thru Paint




13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel osr
Poor Previous Repair
Poor Paint



15: Door osr
Poor Previous Repair
Poor Paint




16: Door osf
Chipped
Edge Chip



17: Wing osf
Dented
Between 10mm + 30mm



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK