

# VEHICLE INSPECTION REPORT

GY71ZRR

## MG Mg 3 EXCITE VTI-TECH

### Inspection

Serious Damage? No

### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 5

### Details

Reg. date	24/11/2021	VIN	LSJZ14U90MS086813	Gearbox	MANUAL
Year	2021	Body Style	Hatchback	Gears	5
Mileage	61,184 Miles Warranted	Keys	2	Doors	5
Fuel Type	Petrol	Service history	None		
Colour	BLACK	MOT Due	11/12/2026		

No Service History

### Tyres



NSF	BUDGET	3.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	2.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint

# No Image


3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint




4: Wing nsf  
Dented  
With Paint Damage



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Chipped  
1 To 5



7: Door nsf  
Dented  
Over 2 UpTo 10mm

# No Image

8: Door nsf  
Scratched  
Over 25mm Not Thru Paint



9: Door nsr  
Dented  
With Paint Damage



10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



12: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



13: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint




14: Boot Lid  
Dented  
Over 30mm




15: Qtr Panel osr  
Dented  
With Paint Damage



16: Wheel osr  
Scratched  
Over 50mm



17: Door osr  
Dented  
With Paint Damage



18: Door osf  
Dented  
Over 30mm



19: Other  
N/A  
N/A



20: Wing osf  
Chipped  
1 To 5

# No Image



21: Wing osf  
Scratched  
Over 25mm Not Thru Paint



23: Screen Front  
Chipped  
UpTo 10mm

24: Carpets Front  
Torn  
Over 10mm

## Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK