

## VEHICLE INSPECTION REPORT

SV66LOH

### Fiat Fullback 2.4 180hp LX Double Cab Pick Up Auto

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Plus VAT
V5	Photocopy

nama  
GRADE 4

#### Details

Reg. date	17/01/2017
Year	2017
Mileage	156,014 Miles Warranted
Fuel Type	Diesel
Colour	BLACK
VIN	ZFAKVJY10G9008397

Body Style	Pick-up
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	2
Last service date	05/01/2024

Last service miles	123,697
MOT Due	17/01/2027
Gearbox	AUTOMATIC
Gears	5

#### £100 ADDITIONAL FEE

Last service 05/01/2024 at 123,697 miles- 2 services. Print  
Photocopy of V5

#### Tyres




NSF	DUNLOP	5.0mm
NSR	DUNLOP	5.0mm
OSF	DUNLOP	5.0mm
OSR	DUNLOP	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Towbar
- Metallic Paint
- Leather seat trim
- Cruise control
- Park assist camera
- Air conditioning
- Drivers airbag
- Front parking sensor
- Rear parking sensor
- Front electric windows
- Passenger airbag
- Heated front seat
- Digital radio
- Rear electric windows
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Carpets Front  
Torn  
Over 10mm



2: Seat Base Cover osf  
Holed  
Over 3mm



3: Bonnet  
Chipped  
Multiple Chips



4: Bumper Front Moulding  
Scratched (Painted)  
Over 25mm Thru Paint



5: Bumper Front  
Chipped  
Multiple Chips



6: Wing osf  
Chipped  
Multiple Chips



7: Door osf  
Scratched  
Over 25mm Thru Paint



8: Door osf  
Dented  
Between 10mm + 30mm



9: Door osr  
Scratched  
Over 25mm Thru Paint



10: C Post osr  
Scratched  
Over 25mm Thru Paint



11: Wheel osr  
Corroded  
Light



12: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



13: Tailgate  
Scratched  
Over 25mm Thru Paint



14: Bumper Rear  
Dented  
With Paint Damage



15: Roof  
Dented  
Over 30mm



16: Qtr Panel nsr  
Dented  
Over 30mm



17: Door nsr  
Scratched  
Over 25mm Thru Paint



18: Door nsf  
Scratched  
UpTo 25mm Thru Paint



19: Wing nsf  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Poor  
Poor

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK