

VEHICLE INSPECTION REPORT

HV63TKY

Mini Countryman 1.6 Cooper 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	15/11/2013
Year	2013
Mileage	82,392 Miles Warranted
Fuel Type	Petrol
Colour	RED
VIN	WMWZB32090WR10451

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	8
Last service date	27/10/2025

Last service miles	81,373
MOT Due	14/11/2026
Gearbox	MANUAL
Gears	6
Doors	5

£65 ADDITIONAL FEE.

Last service 27/10/2025 at 81,373 miles- 8 services. Print

Tyres

NSF	PIRELLI	Worn
NSR	GOODRIDE	3.0mm
OSF	MICHELIN	Worn
OSR	MICHELIN	2.0mm
Spare		

Features


- Cruise control
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Central locking
- PAS
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Leather seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Door Pad osf
Scuffed
UpTo 25mm




2: Bonnet
Chipped
Multiple Chips




3: Bumper Front
Poor Previous Repair
Poor Paint




4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Dented
With Paint Damage




8: Wheel nsr
Scratched
Over 50mm




9: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Dented
Over 2 UpTo 10mm



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Wheel osr
Scratched
Up To 50mm




14: Door osr
Dented
With Paint Damage



15: Roof
Dented
Hail - Moderate



16: Door osf
Chipped
1 To 5



17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



20: Screen Front
Cracked
Replace

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK