

# VEHICLE INSPECTION REPORT

LG67LXY

## Audi A3 1.5 TFSI S Line 5dr

### Inspection

Serious Damage? No

### Vehicle

VAT	Margin
V5	Present

nama  
GRADE  
2

### Details

Reg. date	29/09/2017
Year	2017
Mileage	137,853 Miles Warranted
Fuel Type	Petrol
Colour	BLACK
VIN	WAUZZZ8V7JA042014

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	8
Last service date	20/08/2025

Last service miles	129,243
MOT Due	28/09/2026
Gearbox	MANUAL
Gears	6
Doors	5

£65 ADDITIONAL FEE.

Last service 20/08/2025 at 129,243 miles- 8 services (4 main dealer) Print

### Tyres




NSF	BUDGET	Worn
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


• Bluetooth connection	• Cruise control	• Front parking sensor	• Navigation system
• PAS	• Rear parking sensor	• Rear wiper	• Steering wheel mounted controls
• Audio remote control	• Body coloured bumpers	• Electric door mirrors	• Air conditioning
• Climate control	• Front armrest	• Front electric windows	• Front head restraints
• Height adjustable drivers seat	• Rear electric windows	• Rear headrests	• Metallic Paint
• 3x3 point rear seat belts	• ABS	• Curtain airbags	• Drivers airbag
• Isofix child seat anchor points	• Passenger airbag	• Traction control	• Central locking
• Remote central locking	• Partial leather seat trim	• Alloy wheels	

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

No Image

2: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

# No Image



3: Boot Lid  
Scratched  
Over 25mm Not Thru Paint


4: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm

# No Image



5: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

6: Wheel osr  
Scratched  
Over 50mm



7: Door osr  
Dented  
Over 2 UpTo 10mm

# No Image


8: Door osr  
Scratched  
Over 25mm Not Thru Paint



9: Door osf  
Chipped  
1 To 5

No Image

10: Door osf  
Scratched  
Over 25mm Not Thru Paint



11: Wing osf  
Chipped  
1 To 5



12: Wheel osf  
Scratched  
Over 50mm



13: Bonnet  
Chipped  
1 To 5



14: Bumper Front  
Chipped  
Multiple Chips

# No Image




15: Bumper Front  
Scratched  
Over 25mm Not Thru Paint


16: Wheel nsf  
Scratched  
Over 50mm




17: Wing nsf  
Chipped  
1 To 5



18: Door nsf  
Chipped  
1 To 5



19: Door nsf  
Scratched  
Over 25mm Not Thru Paint



20: Door nsr  
Chipped  
1 To 5

# No Image

21: Door nsr  
Scratched  
Over 25mm Not Thru Paint




# No Image

22: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm



23: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

24: Wheel nsr  
Scratched  
Over 50mm



25: Bumper Rear  
Insecure  
Action Required

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK