

# VEHICLE INSPECTION REPORT

GM64CXP

## Ford Focus 1.0 EcoBoost Zetec 5dr

### Inspection

Serious Damage? No

### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 4

### Details

Reg. date	28/02/2015
Year	2015
Mileage	37,428 Miles Warranted
Fuel Type	Petrol
Colour	BLACK
VIN	WF05XXGCC5EA28975

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	7
Last service date	27/02/2023

Last service miles	29,254
MOT Due	27/02/2026
Gearbox	MANUAL
Gears	5
Doors	5

### £100 ADDITIONAL FEE

Last service 27/02/2023 at 29,254 miles- 7 main dealer services. Book

### Tyres




NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Poor Previous Repair  
Poor Paint



2: Boot Lid  
Dented  
Over 2 UpTo 10mm



3: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm

No Image

4: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint




5: Wheel osr  
Scratched  
Over 50mm



6: Door osr  
Chipped  
1 To 5



7: Door osr  
Dented  
Over 2 UpTo 10mm



8: Door osf  
Poor Previous Repair  
Poor Paint



9: Wing osf  
Scratched  
UpTo 25mm Thru Paint

No Image


10: Wing osf  
Scratched  
Over 25mm Not Thru Paint



11: Wheel osf  
Scratched  
Over 50mm



12: Bumper Front  
Scratched  
25 to 100mm Thru Paint



13: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



14: Bonnet  
Chipped  
1 To 5




15: Wing nsf  
Chipped  
1 To 5

No Image

16: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



17: Wheel nsf  
Scratched  
Over 50mm



18: Door nsf  
Chipped  
Multiple Chips



19: Door nsr  
Dented  
With Paint Damage



20: Qtr Panel nsr  
Chipped  
1 To 5

# No Image



21: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

22: Wheel nsr  
Scratched  
Over 50mm

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK