

VEHICLE INSPECTION REPORT

LV21XNC

Ford Mondeo 2.0 EcoBlue ST-Line Edition 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 3

Details

Reg. date	28/04/2021
Year	2021
Mileage	31,021 Miles Warranted
Fuel Type	Diesel
Colour	BLACK
VIN	WF0EXXWPCEMJ43089

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	3
Last service date	24/04/2025

Last service miles	25,234
MOT Due	27/04/2026
Gearbox	MANUAL
Gears	6
Doors	5

£65 ADDITIONAL FEE. Last service 24/04/2025 at 25234 miles (3 services (2 main dealer)).

Tyres

NSF	BUDGET	5.0mm
NSR	AUTOGREEN	5.0mm
OSF	BUDGET	5.0mm
OSR	AUTOGREEN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Partial leather seat trim
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belt points
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsr
Poor Previous Repair
Rippled UpTo 30%



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Chipped
1 To 5




9: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Tailgate
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
UpTo 25mm Thru Paint



15: Door osf
Dented
Between 10mm + 30mm



16: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK