

VEHICLE INSPECTION REPORT

DE15UCR

Audi A5 3.0 TDI 245 Quattro S Line 5dr S Tronic [5 Seat]

Inspection	Vehicle	nama GRADE 3
Serious Damage?	VAT	Margin
No	V5	Present

Details

Reg. date	31/03/2015	Body Style	Hatchback	Last service miles	106,718
Year	2015	Keys	2	MOT Due	16/06/2026
Mileage	116,517 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	SILVER	Number of stamps	7	Doors	5
VIN	WAUZZZ8T2FA050463	Last service date	10/06/2025		

Last service 10/06/2025 at 106,718 miles- 7 services. Print

Tyres

NSF	BRIDGESTONE	2.0mm
NSR	BRIDGESTONE	3.0mm
OSF	BUDGET	3.0mm
OSR	BRIDGESTONE	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Chipped
1 To 5

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Up To 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Chipped
1 To 5



14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Wheel osr
Scratched
Up To 50mm




16: Door osr
Poor Previous Repair
Poor Paint



17: Door osf
Dented
Over 2 UpTo 10mm

No Image

18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK