

VEHICLE INSPECTION REPORT

PJ11LGE

Nissan Qashqai 1.5 dCi [110] N-Tec 5dr

Inspection	Vehicle	nama GRADE
Serious Damage?	VAT	Margin
No	V5	Present

Details

Reg. date	28/06/2011	Body Style	Hatchback	Last service miles	92,965
Year	2011	Keys	2	MOT Due	29/12/2026
Mileage	93,498 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	15	Doors	5
VIN	SJNFCAJ10U2321046	Last service date	19/01/2025		

Last Service - 19.01.2025 at 92965 miles (15 services) Reverse camera faulty

Tyres



NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	NEXEN	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Door nsr
Dented
Between 10mm + 30mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Scratched
Over 25mm Thru Paint




14: Door osf
Scratched
Over 25mm Thru Paint



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Scratched
UpTo 25mm Thru Paint



17: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		