



VEHICLE INSPECTION REPORT

LB20NDV

Kia E-Niro 150kW 4 64kWh 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	15/07/2020	Body Style	Estate	Last service miles	14,526
Year	2020	Keys	2	MOT Due	13/06/2026
Mileage	16,082 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Printout	Gears	1
Colour	BLACK	Number of stamps	5		
VIN	KNACC81GUL5042117	Last service date	30/05/2025		

last service 30/5/25 @ 14,526 miles (5 main dealer) print 3 pin plug charging cable in boot

Tyres

NSF	MICHELIN	3.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Front parking sensor
- PAS
- Audio remote control
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Bumper Rear Moulding
Broken
Replace



3: Boot Lid
Chipped
1 To 5



4: Qtr Panel osr
Chipped
1 To 5



5: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



6: Wheel osr
Scratched
Up To 50mm



7: Door osr
Dented
With Paint Damage




8: Door osf
Chipped
Multiple Chips



9: Roof
Dented
Hail - Moderate



10: Wing osf
Chipped
1 To 5




11: Wing osf
Scratched
Over 25mm Not Thru Paint



12: Wheel osr
Scratched
Up To 50mm




13: Bumper Front
Scratched
25 to 100mm Thru Paint



14: Bumper Front
Scratched
Over 25mm Not Thru Paint



15: Bonnet
Chipped
1 To 5



16: Wing nsf
Scratched
Over 25mm Not Thru Paint



17: Wheel nsf
Scratched
Over 50mm



18: Door nsf
Dented
Over 30mm



19: Door nsr
Dented
With Paint Damage



20: Qtr Panel nsr
Chipped
1 To 5

No Image



21: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

22: Wheel nsr
Scratched
Up To 50mm



23: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK