

# VEHICLE INSPECTION REPORT

SD65UJX

## Vauxhall Corsa 1.2 Limited Edition 3dr

Inspection	Vehicle	nama GRADE 3
Serious Damage?	VAT	Margin
No	V5	Present

### Details

Reg. date	17/09/2015	Body Style	Hatchback	Last service miles	62,051
Year	2015	Keys	2	MOT Due	21/10/2026
Mileage	62,331 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	6	Doors	3
VIN	W0L0XEP08G6002011	Last service date	31/10/2025		

last service 31/10/25 @ 62,051 miles (6 services 1 main dealer) book and print

### Tyres


NSF	COMFORSER	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cruise control
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips




2: Bumper Front  
Chipped  
Multiple Chips

# No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint




5: Wing nsf  
Chipped  
1 To 5




7: Door nsf  
Scratched  
Over 25mm Not Thru Paint



4: Wheel nsf  
Scratched  
Up To 50mm



6: Door nsf  
Chipped  
1 To 5



8: Qtr Panel nsf  
Chipped  
1 To 5

# No Image



9: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

10: Wheel nsr  
Scratched  
Up To 50mm



11: Bumper Rear  
Chipped  
1 To 5

# No Image

12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint




13: Boot Lid  
Chipped  
1 To 5



14: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm


# No Image

15: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



16: Wheel osr  
Scratched  
Up To 50mm

17: Door osf  
Dented  
Over 30mm



18: Wheel osf  
Scratched  
Up To 50mm

19: Wing osf  
Chipped  
1 To 5

## Interior

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK