

VEHICLE INSPECTION REPORT

EN12CXJ

Hyundai i30 1.4 Active 5dr

Inspection	Vehicle		GRADE 5
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	01/07/2012	Body Style	Hatchback	Last service miles	114,000
Year	2012	Keys	2	MOT Due	31/08/2026
Mileage	121,619 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Electronic / Online	Gears	6
Colour	BLACK	Number of stamps	1	Doors	5
VIN	TMAD251ALDJ019863	Last service date	28/08/2024		

£100 ADDITIONAL FEE

Last service 28/08/2024 at 114,000 miles- 1 service confirmed by RDS, Hastings Eml on and possible power steering fault(notchy while turning)

Car has been plugged in and detects camshaft position timing over advanced or system performance bank 1

Tyres


NSF	NEXEN	2.0mm
NSR	NEXEN	4.0mm
OSF	NEXEN	2.0mm
OSR	NEXEN	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
With Paint Damage



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage




8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Scratched
25 to 100mm Thru Paint




11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Dented
Over 2 UpTo 10mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Dented
With Paint Damage



16: Door osf
Poor Previous Repair
Poor Paint




17: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



18: A Post osf
Scratched
UpTo 25mm Thru Paint



19: Wing osf
Chipped
1 To 5



20: Wing osf
Scratched
Over 25mm Not Thru Paint



21: Wheel osf
Scratched
Over 50mm



22: Screen Front
Chipped
UpTo 10mm



23: Carpets Front
Torn
Over 10mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	Fault