

# VEHICLE INSPECTION REPORT

HG12WGK

## Nissan Juke 1.6 DiG-T Kuro 5dr

### Inspection

Serious Damage? No

### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 5

### Details

Reg. date	30/06/2012
Year	2012
Mileage	131,573 Miles Warranted
Fuel Type	Petrol
Colour	RED
VIN	SJNFAAF15U6137830

Body Style	Hatchback
Keys	1
Service history	Yes
Service documents	Service Book
Number of stamps	7
Last service date	13/05/2022

Last service miles	85,100
MOT Due	21/04/2026
Gearbox	MANUAL
Gears	6
Doors	5

### £100 ADDITIONAL FEE

Last Service - 13.05.2022 at 85100 miles (7 services) Intermittent noise from engine  
glovebox broken

### Tyres

NSF	BUDGET	2.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim

## Photos






## Condition Check



## Damage Photos



1: Seat Base Cover off  
Scuffed  
Over 25mm




2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Cracked  
UpTo 25mm



4: Other  
N/A  
N/A



5: Wing nsf  
Chipped  
Multiple Chips



6: Wheel nsf  
Scratched  
Over 50mm



7: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



8: Door nsf  
Dented  
With Paint Damage



9: Door nsr  
Dented  
With Paint Damage



10: Wheel nsr  
Scratched  
Over 50mm




11: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



12: Bumper Rear  
Scratched  
Over 100mm Thru Paint



13: Boot Lid  
Dented  
Over 2 UpTo 10mm



14: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



15: Wheel osr  
Scratched  
Over 50mm



16: Door osr  
Chipped  
Multiple Chips



17: Door osf  
Dented  
Over 30mm



18: Roof  
Scratched  
Over 25mm Thru Paint



19: Wing osf  
Scratched  
Over 25mm Thru Paint



20: Wheel osf  
Scratched  
Over 50mm



21: Seat Base Cover nsf

Scuffed

UpTo 25mm

## Interior

Carpet Condition

Average

Upholstery Condition

Odour

Average

No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK