

VEHICLE INSPECTION REPORT

GV03AXF

MG Mgtf 135

Inspection

Serious Damage? No

Vehicle

nama
GRADE 5

VAT	Margin
V5	Present

Details

Reg. date	31/03/2003
Year	2003
Mileage	69,198 Miles Warranted
Fuel Type	Petrol
Colour	BLUE
VIN	SARRDWBKC3D616283

Body Style	Sports	Last service miles	69,166
Keys	2	MOT Due	27/11/2026
Service history	Yes	Gearbox	MANUAL
Service documents	Printout	Gears	5
Number of stamps	4		
Last service date	31/03/2025		

£50 ADDITIONAL FEE

Last service 31/03/2025 at 69,166 miles- 4 services. Book and print Unable to open roof and bonnet
Overheating head gasket faulty

Tyres

NSF	RAPID	5.0mm
NSR	FALKEN	5.0mm
OSF	RAPID	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- PAS
- Front fog lights
- Steering wheel rake adjustment
- Central locking
- Radio/CD
- Front armrest
- Steering wheel reach adjustment
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Leather seat trim
- Electric door mirrors
- Front head restraints
- Drivers airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Bumper Front
Insecure
Action Required




4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Rusted
Over 5mm



6: Door nsf
Dented
Over 30mm




7: Qtr Panel nsr
Scratched
Rusted



8: Wheel nsr
Scratched
Up To 50mm




9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Boot Lid
Scratched
Over 25mm Thru Paint



11: Panel Rear
Rusted
Over 5mm



12: Qtr Panel osr
Rusted
Over 5mm



13: Wheel osr
Scratched
Up To 50mm



14: Door osr
Dented
Over 30mm



15: Wing osf
Chipped
Multiple Chips



16: Wheel osf
Scratched
Over 50mm



17: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



18: A Post os
Rusted
Over 5mm



19: Roof Soft Top
Scuffed
Over 25mm



20: Bonnet
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK