

VEHICLE INSPECTION REPORT

GP56PXK

Honda Jazz 1.4 i-DSi Sport 5dr CVT-7

Inspection	Vehicle		GRADE 5
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	12/01/2007	Body Style	Hatchback	Last service miles	60,755
Year	2007	Keys	2	MOT Due	12/01/2027
Mileage	61,121 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Service Book	Gears	1
Colour	BLACK	Number of stamps	19	Doors	5
VIN	JHMGD18906S247291	Last service date	15/12/2025		

Last Service - 15.12.2025 at 60755 miles (19 services)

Tyres


NSF	AVON	5.0mm
NSR	AUTOGREEN	4.0mm
OSF	AVON	5.0mm
OSR	AUTOGREEN	4.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front head restraints
- Steering wheel rake adjustment
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Air conditioning
- Rear electric windows
- Metallic Paint
- Side airbags
- Alloy wheels
- Radio/CD
- Folding rear seats
- Rear headrests
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Roof
Dented
Between 10mm + 30mm




2: Bonnet
Poor Previous Repair
Paint Flake



3: Bumper Front
Cracked
UpTo 25mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door nsf
Poor Previous Repair
Poor Colour




9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Cracked
Over 25mm



13: Tailgate
Dented
Over 30mm



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osf
Dented
Over 30mm



18: Wing osf
Scratched
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK