

VEHICLE INSPECTION REPORT

GF18CYK

Nissan Qashqai 1.2 DiG-T Tekna+ 5dr Xtronic

Inspection	Vehicle	nama GRADE 4
Serious Damage?	VAT	Margin
No	V5	Present

Details

Reg. date	30/03/2018	Body Style	Hatchback	Last service miles	40,516
Year	2018	Keys	2	MOT Due	16/02/2026
Mileage	45,250 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Service Book	Gears	1
Colour	BLUE	Number of stamps	5	Doors	5
VIN	SJNFEAJ11U2293463	Last service date	14/02/2025		

£65 ADDITIONAL FEE

Last service 14/02/2025 at 40,516 miles- 5 services (3 main dealer) Book

Tyres



NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	WESTLAKE	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Front parking sensor	• Heated front seat
• Navigation system	• Park assist camera	• PAS	• Rear parking sensor
• Rear wiper	• Steering wheel mounted controls	• Digital radio	• Body coloured bumpers
• Electric door mirrors	• Fixed panoramic glass roof	• Front fog lights	• Roof rails
• Air conditioning	• Electrically adjustable drivers seat	• Electrically adjustable passenger seat	• Folding rear seats
• Front armrest	• Front electric windows	• Front head restraints	• Height adjustable drivers seat
• Rear electric windows	• Rear headrests	• Steering wheel rake adjustment	• Steering wheel reach adjustment
• Metallic Paint	• 3x3 point rear seat belts	• ABS	• Drivers airbag
• ESP	• Isofix child seat anchor points	• Passenger airbag	• Side airbags
• Tyre pressure monitor	• Central locking	• Remote central locking	• Leather seat trim
• Alloy wheels			

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Over 30mm



6: Door nsr
Scratched
Over 25mm Thru Paint




7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Tailgate
Scratched
UpTo 25mm Thru Paint



10: Roof
Scratched
Over 25mm Thru Paint



11: B Post osr
Dented
Over 30mm




12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
UpTo 25mm Thru Paint



15: Door osf
Dented
Between 10mm + 30mm



16: Wing osf
Scratched
UpTo 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		