

VEHICLE INSPECTION REPORT

DN69LMF

Vauxhall Astra 1.4T 16V 150 SRi Vx-line Nav 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 3

Details

Reg. date	30/09/2019
Year	2019
Mileage	56,238 Miles Warranted
Fuel Type	Petrol
Colour	BLACK
VIN	W0VBF6EC4KG396320

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	3
Last service date	08/10/2025

Last service miles	53,920
MOT Due	10/10/2026
Gearbox	MANUAL
Gears	6
Doors	5

£65 ADDITIONAL FEE.

Last service 08/10/2025 at 53,920 miles- 3 services (2 main dealer) Print

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Chipped
1 To 5

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Chipped
1 To 5




8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Chipped
Multiple Chips



10: Qtr Panel nsr
Dented
Over 2 UpTo 10mm




11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Chipped
Multiple Chips




14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Boot Lid
Chipped
1 To 5




16: Qtr Panel osr
Dented
2 Or Less UpTo 10mm




17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Poor Previous Repair
Poor Paint



20: Door osf
Dented
Over 2 UpTo 10mm

No Image



21: Door osf
Scratched
Over 25mm Not Thru Paint

22: Wing osf
Chipped
1 To 5



23: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK