

VEHICLE INSPECTION REPORT

SE18WWV

Ford Kuga 1.5 TDCi ST-Line X 5dr Auto 2WD

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 3

Details

Reg. date	14/05/2018
Year	2018
Mileage	61,201 Miles Warranted
Fuel Type	Diesel
Colour	GREY
VIN	WF0AXXWPMAJS44393

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	3
Last service date	05/08/2021

Last service miles	29,598
MOT Due	14/03/2026
Gearbox	AUTOMATIC
Gears	6
Doors	5

£100 ADDITIONAL FEE

Last service 05/08/2021 at 29,598 miles- 3 services (2 main dealer) Book

Tyres

NSF	CONTINENTAL	5.0mm
NSR	HANKOOK	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	ROYALBLACK	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Poor Colour



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Screen Front
Chipped
UpTo 10mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
UpTo 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Chipped
Edge Chip



12: Door osf
Dented
Over 30mm



13: Wheel osf
Scratched
Over 50mm



14: Wing osf
Chipped
1 To 5



15: A Post os
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		